

# Noyer Walnut Timber LED Oyster & Pendant

<b>Name</b>	Noyer
<b>Material</b>	Walnut Timber** + Aluminium
<b>Colour</b>	Walnut** + White
<b>IP Rating</b>	IP20
<b>Cable Length</b>	3000mm Adjustable (Pendant Model Only)
<b>Colour Temp</b>	<div style="display: flex; gap: 5px;"> <div style="width: 10px; height: 10px; background-color: #FFD700; border: 1px solid black;"></div> 3000k           <div style="width: 10px; height: 10px; background-color: #ADD8E6; border: 1px solid black;"></div> 4000k           <div style="width: 10px; height: 10px; background-color: #00CED1; border: 1px solid black;"></div> 5500k         </div>
<b>IK Rating</b>	IK05
<b>Installation Type</b>	Ceiling - Surface Mounted
<b>Diffuser Type</b>	Polycarbonate
<b>Lamp Base</b>	Built in LED
<b>Max Wattage</b>	35w
<b>Protection Class</b>	1 (Requires Earth)
<b>Lamp Expectancy</b>	<30,000hrs*
<b>CRI</b>	CRI>80
<b>Dimmable</b>	Triac Dimmable
<b>SDCM</b>	<6
<b>UGR</b>	<25
<b>Warranty</b>	3 Years Replacement*




HV5872T






HV5872T-PDT

## HV5872T Dimensions



## HV5872T-PDT Dimensions



**i** Walnut is a natural timber and will vary in colour, grain pattern, texture, and tone. Natural characteristics such as knots, mineral streaks and colour variation are inherent to the material and are not considered defects. These variations are part of the beauty and uniqueness of each piece.

Warranty  
Terms & Conditions

Website

## Product Ordering

Image	Part Number	Colour Temp	Lumens	Input Voltage	Beam Angle	Included LED	Barcode
	<b>HV5872T</b>	3000k 4000k 5500k	3000lm 3200lm 3100lm	240v	120°	<b>TRI Colour</b> 35w Built in LED	9350418034953
	<b>HV5872T-PDT</b>	3000k 4000k 5500k	3000lm 3200lm 3100lm	240v	120°	<b>TRI Colour</b> 35w Built in LED	9350418034915

## Optional Havit Compatible Accessories

Image	Part Number	Description
<b>Dimmer</b>		
	<b>HV9625</b>	300W LED Dial Dimmer

\*See Warranty Terms & Conditions for More Information

\*\*Variations in colour, grain, and natural markings are inherent to walnut timber and are not considered defects.

